















KABINA PIĘCIOKĄTNA



g MONTAŻ BEZ PROGU



h WYMIAR DO OSI SZYBY



i WYMIAR DO OSI SZYBY




TABELA ROZMIARÓW:

LIGHT GOLD

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	C	D	W	H	X1*	X2*
K-1667	2	80x80x200	czyste 6mm	77,5-78,7	77,5-78,7	32	32	58	195	76,2-77,7	76,2-77,7
K-1668	2	90x90x200	czyste 6mm	87,5-88,7	87,5-88,7	42	42	58	195	86,2-87,7	86,2-87,7
K-1669	2	100x80x200	czyste 6mm	97,5-98,7	77,5-78,7	52	32	58	195	96,2-97,7	76,2-77,7

* X1, X2 - WYMIAR DO OSI SZYB

GOLD BRUSHED

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	C	D	W	H	X1*	X2*
K-3585	2	80x80x200	czyste 6mm	77,5-78,7	77,5-78,7	32	32	58	195	76,2-77,7	76,2-77,7
K-3586	2	90x90x200	czyste 6mm	87,5-88,7	87,5-88,7	42	42	58	195	86,2-87,7	86,2-87,7
K-3587	2	100x80x200	czyste 6mm	97,5-98,7	77,5-78,7	52	32	58	195	96,2-97,7	76,2-77,7

* X1, X2 - WYMIAR DO OSI SZYB

COPPER BRUSHED

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	C	D	W	H	X1*	X2*
K-1704	2	80x80x200	czyste 6mm	77,5-78,7	77,5-78,7	32	32	58	195	76,2-77,7	76,2-77,7
K-1705	2	90x90x200	czyste 6mm	87,5-88,7	87,5-88,7	42	42	58	195	86,2-87,7	86,2-87,7
K-1706	2	100x80x200	czyste 6mm	97,5-98,7	77,5-78,7	52	32	58	195	96,2-97,7	76,2-77,7

* X1, X2 - WYMIAR DO OSI SZYB

GUNMETAL BRUSHED

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	C	D	W	H	X1*	X2*
K-1711	2	80x80x200	czyste 6mm	77,5-78,7	77,5-78,7	32	32	58	195	76,2-77,7	76,2-77,7
K-1712	2	90x90x200	czyste 6mm	87,5-88,7	87,5-88,7	42	42	58	195	86,2-87,7	86,2-87,7
K-1713	2	100x80x200	czyste 6mm	97,5-98,7	77,5-78,7	52	32	58	195	96,2-97,7	76,2-77,7

* X1, X2 - WYMIAR DO OSI SZYB