

















TABELA ROZMIARÓW:

CHROME

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	C	W	H	X1*	X2*
K-1254	1/L	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-1255	1/L	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-1588	1/L	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-1589	1/L	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-1258	1/L	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-1259	1/L	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-1590	1/L	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-1591	1/L	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-1262	1/L	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-1263	1/L	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-1592	1/L	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-1593	1/L	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118
K-1266	1/P	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-1267	1/P	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-1594	1/P	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-1595	1/P	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-1270	1/P	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-1271	1/P	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-1596	1/P	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-1597	1/P	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-1274	1/P	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-1275	1/P	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-1598	1/P	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-1599	1/P	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118

* X1, X2 - WYMIAR DO OSI SZYB

TABELA ROZMIARÓW:

BLACK

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	C	W	H	X1*	X2*
K-1334	1/L	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-1335	1/L	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-1612	1/L	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-1613	1/L	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-1338	1/L	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-1339	1/L	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-1614	1/L	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-1615	1/L	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-1342	1/L	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-1343	1/L	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-1616	1/L	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-1617	1/L	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118
K-1346	1/P	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-1347	1/P	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-1618	1/P	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-1619	1/P	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-1350	1/P	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-1351	1/P	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-1620	1/P	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-1621	1/P	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-1354	1/P	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-1355	1/P	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-1622	1/P	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-1623	1/P	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118

* X1, X2 - WYMIAR DO OSI SZYB

TABELA ROZMIARÓW:

WHITE

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	C	W	H	X1*	X2*
K-1414	1/L	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-1415	1/L	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-1624	1/L	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-1625	1/L	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-1418	1/L	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-1419	1/L	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-1626	1/L	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-1627	1/L	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-1422	1/L	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-1423	1/L	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-1628	1/L	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-1629	1/L	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118
K-1426	1/P	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-1427	1/P	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-1630	1/P	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-1631	1/P	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-1430	1/P	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-1431	1/P	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-1632	1/P	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-1633	1/P	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-1434	1/P	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-1435	1/P	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-1634	1/P	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-1635	1/P	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118

* X1, X2 - WYMIAR DO OSI SZYB

TABELA ROZMIARÓW:

LIGHT GOLD

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	C	W	H	X1*	X2*
K-1494	1/L	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-1495	1/L	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-1552	1/L	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-1553	1/L	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-1498	1/L	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-1499	1/L	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-1554	1/L	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-1555	1/L	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-1502	1/L	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-1503	1/L	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-1556	1/L	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-1557	1/L	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118
K-1506	1/P	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-1507	1/P	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-1558	1/P	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-1559	1/P	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-1510	1/P	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-1511	1/P	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-1560	1/P	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-1561	1/P	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-1514	1/P	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-1515	1/P	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-1562	1/P	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-1563	1/P	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118

* X1, X2 - WYMIAR DO OSI SZYB

TABELA ROZMIARÓW:

GOLD BRUSHED

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	C	W	H	X1*	X2*
K-3942	1/L	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-3943	1/L	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-3944	1/L	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-3945	1/L	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-3946	1/L	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-3947	1/L	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-3948	1/L	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-3949	1/L	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-3950	1/L	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-3951	1/L	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-3952	1/L	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-3953	1/L	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118
K-3954	1/P	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-3955	1/P	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-3956	1/P	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-3957	1/P	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-3958	1/P	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-3959	1/P	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-3960	1/P	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-3961	1/P	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-3962	1/P	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-3963	1/P	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-3964	1/P	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-3965	1/P	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118

* X1, X2 - WYMIAR DO OSI SZYB

TABELA ROZMIARÓW:
COPPER BRUSHED

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	C	W	H	X1*	X2*
K-4123	1/L	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-4124	1/L	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-4125	1/L	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-4126	1/L	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-4127	1/L	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-4128	1/L	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-4129	1/L	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-4130	1/L	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-4131	1/L	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-4132	1/L	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-4133	1/L	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-4134	1/L	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118
K-4135	1/P	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-4136	1/P	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-4137	1/P	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-4138	1/P	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-4139	1/P	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-4140	1/P	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-4141	1/P	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-4142	1/P	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-4143	1/P	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-4144	1/P	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-4145	1/P	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-4146	1/P	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118

* X1, X2 - WYMIAR DO OSI SZYB

TABELA ROZMIARÓW:

GUNMETAL BRUSHED

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	C	W	H	X1*	X2*
K-4932	1/L	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-4933	1/L	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-4934	1/L	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-4935	1/L	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-4936	1/L	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-4937	1/L	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-4938	1/L	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-4939	1/L	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-4940	1/L	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-4941	1/L	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-4942	1/L	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-4943	1/L	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118
K-4944	1/P	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-4945	1/P	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-4946	1/P	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-4947	1/P	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-4948	1/P	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-4949	1/P	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-4950	1/P	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-4951	1/P	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-4952	1/P	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-4953	1/P	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-4954	1/P	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-4955	1/P	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118

* X1, X2 - WYMIAR DO OSI SZYB