
















TABELA ROZMIARÓW:

CHROME

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	C	W	H	X1*	X2*
K-0870	1/L	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-0882	1/P	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-0871	1/L	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-0883	1/P	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-1576	1/L	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-1582	1/P	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-1577	1/L	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-1583	1/P	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-0874	1/L	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-0886	1/P	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-0875	1/L	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-0887	1/P	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-1578	1/L	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-1584	1/P	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-1579	1/L	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-1585	1/P	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-0878	1/L	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-0890	1/P	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-0879	1/L	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-0891	1/P	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-1580	1/L	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-1586	1/P	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-1581	1/L	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118
K-1587	1/P	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118

* X1, X2 - WYMIAR DO OSI SZYB

TABELA ROZMIARÓW:

BLACK

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	C	W	H	X1*	X2*
K-0966	1/L	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-0978	1/P	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-0967	1/L	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-0979	1/P	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-1600	1/L	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-1606	1/P	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-1601	1/L	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-1607	1/P	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-0970	1/L	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-0982	1/P	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-0971	1/L	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-0983	1/P	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-1602	1/L	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-1608	1/P	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-1603	1/L	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-1609	1/P	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-0974	1/L	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-0986	1/P	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-0975	1/L	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-0987	1/P	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-1604	1/L	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-1610	1/P	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-1605	1/L	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118
K-1611	1/P	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118

* X1, X2 - WYMIAR DO OSI SZYB

TABELA ROZMIARÓW:
WHITE

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	C	W	H	X1*	X2*
K-1062	1/L	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-1074	1/P	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-1063	1/L	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-1075	1/P	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-1564	1/L	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-1570	1/P	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-1565	1/L	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-1571	1/P	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-1066	1/L	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-1078	1/P	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-1067	1/L	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-1079	1/P	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-1566	1/L	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-1572	1/P	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-1567	1/L	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-1573	1/P	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-1070	1/L	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-1082	1/P	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-1071	1/L	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-1083	1/P	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-1568	1/L	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-1574	1/P	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-1569	1/L	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118
K-1575	1/P	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118

* X1, X2 - WYMIAR DO OSI SZYB

TABELA ROZMIARÓW:

LIGHT GOLD

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	C	W	H	X1*	X2*
K-1158	1/L	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-1170	1/P	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-1159	1/L	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-1171	1/P	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-1636	1/L	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-1642	1/P	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-1637	1/L	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-1643	1/P	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-1162	1/L	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-1174	1/P	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-1163	1/L	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-1175	1/P	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-1638	1/L	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-1644	1/P	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-1639	1/L	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-1645	1/P	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-1166	1/L	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-1178	1/P	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-1167	1/L	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-1179	1/P	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-1640	1/L	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-1646	1/P	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-1641	1/L	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118
K-1647	1/P	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118

* X1, X2 - WYMIAR DO OSI SZYB

TABELA ROZMIARÓW:

GOLD BRUSHED

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	C	W	H	X1*	X2*
K-3918	1/L	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-3919	1/P	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-3920	1/L	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-3921	1/P	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-3922	1/L	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-3923	1/P	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-3924	1/L	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-3925	1/P	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-3926	1/L	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-3927	1/P	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-3928	1/L	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-3929	1/P	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-3930	1/L	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-3931	1/P	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-3932	1/L	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-3933	1/P	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-3934	1/L	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-3935	1/P	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-3936	1/L	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-3937	1/P	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-3938	1/L	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-3939	1/P	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-3940	1/L	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118
K-3941	1/P	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118

* X1, X2 - WYMIAR DO OSI SZYB

TABELA ROZMIARÓW:

COPPER BRUSHED

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	C	W	H	X1*	X2*
K-4099	1/L	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-4100	1/P	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-4101	1/L	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-4102	1/P	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-4103	1/L	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-4104	1/P	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-4105	1/L	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-4106	1/P	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-4107	1/L	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-4108	1/P	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-4109	1/L	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-4110	1/P	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-4111	1/L	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-4112	1/P	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-4113	1/L	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-4114	1/P	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-4115	1/L	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-4116	1/P	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-4117	1/L	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-4118	1/P	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-4119	1/L	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-4120	1/P	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-4121	1/L	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118
K-4122	1/P	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118

* X1, X2 - WYMIAR DO OSI SZYB

TABELA ROZMIARÓW:
GUNMETAL BRUSHED

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	C	W	H	X1*	X2*
K-4908	1/L	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-4909	1/P	100x90x200	czyste 6mm	98,5-100	88-90	44	40	200	97,5-99	86-88
K-4910	1/L	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-4911	1/P	100x100x200	czyste 6mm	98,5-100	98-100	44	40	200	97,5-99	96-98
K-4912	1/L	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-4913	1/P	100x110x200	czyste 6mm	98,5-100	108-110	44	40	200	97,5-99	106-108
K-4914	1/L	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-4915	1/P	100x120x200	czyste 6mm	98,5-100	118-120	44	40	200	97,5-99	116-118
K-4916	1/L	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-4917	1/P	110x90x200	czyste 6mm	108,5-110	88-90	49	45	200	107,5-109	86-88
K-4918	1/L	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-4919	1/P	110x100x200	czyste 6mm	108,5-110	98-100	49	45	200	107,5-109	96-98
K-4920	1/L	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-4921	1/P	110x110x200	czyste 6mm	108,5-110	108-110	49	45	200	107,5-109	106-108
K-4922	1/L	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-4923	1/P	110x120x200	czyste 6mm	108,5-110	118-120	49	45	200	107,5-109	116-118
K-4924	1/L	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-4925	1/P	120x90x200	czyste 6mm	118,5-120	88-90	54	50	200	117,5-119	86-88
K-4926	1/L	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-4927	1/P	120x100x200	czyste 6mm	118,5-120	98-100	54	50	200	117,5-119	96-98
K-4928	1/L	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-4929	1/P	120x110x200	czyste 6mm	118,5-120	108-110	54	50	200	117,5-119	106-108
K-4930	1/L	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118
K-4931	1/P	120x120x200	czyste 6mm	118,5-120	118-120	54	50	200	117,5-119	116-118

* X1, X2 - WYMIAR DO OSI SZYB